


No 3 of 2026 | 13th March 2026

Fender No.2 Damage

Mariners are advised No.2 fender, on the south side, of Loch Ryan Pier is out of service until further notice. No.2 fender is identified by the yellow highlight below.



All vessels are requested to berth with care and to remove the use of No.2 fender within their normal berthing procedure.

Repairs are underway and mariners will be notified when the repair is complete.

Issued on behalf of the Harbour Authority

Harbourmaster.lrp@stenaline.com